

## Important safety advice

### Optional safety measure for auxiliary mixer unit installed on high shear mixer - concerning:

- Compact plant ICS150, IC300, IC650, IC1100, IC1400
- High shear mixer HCM50, HCM100, HCM300, HCM600

Häny AG emphasizes great importance to the quality and safety of its products. Customer satisfaction is our highest priority. Therefore, we would like to inform you about an optional safety-related measure.


During one of our safety reassessments, we have found that when the cover/lattice insert of the filling opening is removed, the shaft and the mixing wheel of the auxiliary mixer unit does not come to a standstill in the required time. Therefore, it cannot be completely ruled out, that in rare cases injuries could occur if the cover is removed very quickly and the moving parts, which had not yet come to a standstill, are touched.

In order to meet our responsibility to the customer, we have decided to provide instructions for the modification of the concerned plants and to provide the necessary parts free of charge. Alternatively, the existing motor could be replaced with a brake motor which does not require any further changes to the plant.

**The high shear mixer with installed auxiliary mixer unit concerned may no longer be used and/or passed on without one of the above modifications.** If you have resold or passed on a potentially affected plant, please forward this safety advice to the receiver as quick as possible to ensure that the affected plant is no longer being used.

Plants produced up to March 2017 are affected. They can be clearly identified by the serial number (see reverse):

The plant type as well as the serial number can be found on the machine plate as follows:



**Legend:**

- 1. Pump/unit type
- 2. Serial No.
- 3. Part No.

**Compact plant IC**

Type	No		Remarks
XXXX-XX-XX	XX.XXXXXXX/XXX		
2515-AZ-00	17.1126199/001		Example

**High shear mixer HCM**

Type	Serial No.	Part No.	Remarks
XXX XXX	XX.XXXXX/XXX	XXXX-XX-XX	
HCM 600	17.41155/001	2516-WB-91	Example

If the first digit of the No resp. Serial No. (XX) is a "0" or "1" and the second digit (XX) is in the range from "0" to "7", and the plant has an auxiliary mixer unit, it is a potentially affected plant.

Häny AG is very sorry for the safety-related measures that have occurred and apologizes to all affected customers.